

United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	F	TILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO	
10/770,888		02/03/2004	Paul Martin Schulte	NTS 0102 PUS	NTS 0102 PUS 1089	
22045	7590	07/13/2005		EXAMINER		
BROOKS 1			TALBOT, MICHAEL			
TWENTY-S				ART UNIT	PAPER NUMBER	
SOUTHFIELD, MI 48075				3722	3722	

DATE MAILED: 07/13/2005

Please find below and/or attached an Office communication concerning this application or proceeding.

			0
	Application No.	Applicant(s)	
	10/770,888	SCHULTE, PAUL M	MARTIN
Office Action Summary	Examiner	Art Unit	
	Michael W. Talbot	3722	
The MAILING DATE of this communication app Period for Reply	pears on the cover sheet with the	correspondence addr	ress
A SHORTENED STATUTORY PERIOD FOR REPL' THE MAILING DATE OF THIS COMMUNICATION. - Extensions of time may be available under the provisions of 37 CFR 1.1: after SIX (6) MONTHS from the mailing date of this communication. - If the period for reply specified above is less than thirty (30) days, a reply If NO period for reply is specified above, the maximum statutory period of the province of the period for reply within the set or extended period for reply will, by statute any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	36(a). In no event, however, may a reply be ti y within the statutory minimum of thirty (30) da vill apply and will expire SIX (6) MONTHS fron , cause the application to become ABANDONE	mely filed ys will be considered timely. In the mailing date of this com ED (35 U.S.C. § 133).	munication.
Status	•		
1)⊠ Responsive to communication(s) filed on 03 F	ebruary 2004.		
, _ · · · · · · · · · · · · · · · · · ·	action is non-final.		
3) Since this application is in condition for alloward closed in accordance with the practice under E	•		nerits is
Disposition of Claims			
4) ☐ Claim(s) 1-29 is/are pending in the application. 4a) Of the above claim(s) is/are withdraw 5) ☐ Claim(s) is/are allowed. 6) ☐ Claim(s) 1-29 is/are rejected. 7) ☐ Claim(s) is/are objected to. 8) ☐ Claim(s) are subject to restriction and/o	wn from consideration.		
Application Papers			
9)☐ The specification is objected to by the Examine			
10) ☐ The drawing(s) filed on is/are: a) ☐ acc			
Applicant may not request that any objection to the	* '	` ,	
Replacement drawing sheet(s) including the correct 11) The oath or declaration is objected to by the Ex	* * * * * * * * * * * * * * * * * * * *	•	, ,
Priority under 35 U.S.C. § 119			
12) Acknowledgment is made of a claim for foreign a) All b) Some * c) None of: 1. Certified copies of the priority document 2. Certified copies of the priority document 3. Copies of the certified copies of the priority application from the International Bureau * See the attached detailed Office action for a list	s have been received. s have been received in Applicat rity documents have been receiv u (PCT Rule 17.2(a)).	tion No red in this National Si	tage
Attachment(s)			
Notice of References Cited (PTO-892)	4) 🔲 Interview Summary		
2) Notice of Draftsperson's Patent Drawing Review (PTO-948) 3) Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08) Paper No(s)/Mail Date 2.	Paper No(s)/Mail D 5) Notice of Informal I 6) Other:		52)

Page 2

DETAILED ACTION

Specification

1. The disclosure is objected to because of the following informalities:

Refer to page 5, lines 21 and 22, the phrase "the length of the reamer 20 and the diameter d_b of the body 24 is dictated" should be changed to read --the length of the reamer 20 and the diameter d_b of the body 24 are dictated--.

Refer to page 7, lines 1 and 2, the phrase "The array of straight flutes and the array of helical flutes 42 is arranged" should be changed to read --The array of straight flutes and the array of helical flutes 42 are arranged--.

Appropriate correction is required.

Claim Objections

2. Claims 17 and 18 are objected to because of the following informalities:

Refer to claim 17, line 2 and claim 18, line 3, the character reference "the at least one primary flute" should be changed to read --the at least one first flute-- to remain consistent with claim 1 form which it depends therefrom.

Appropriate correction is required.

Claim Rejections - 35 USC § 102

3. The following is a quotation of the appropriate paragraphs of 35 U.S.C. 102 that form the basis for the rejections under this section made in this Office action:

A person shall be entitled to a patent unless -

(b) the invention was patented or described in a printed publication in this or a foreign country or in public use or on sale in this country, more than one year prior to the date of application for patent in the United States.

Claims 1-6,9,10,13,14,16-24 and 27-29 are rejected under 35 U.S.C. 102(b) as being anticipated by Yeo '316. Yeo '316 shows in Figure 1 a rotary cutting tool (10) having a shank (12) for rotation in a first hand direction (15), a cylindrical body extending axially from shank

Art Unit: 3722

having at least one first flute (28) with at least one first flute cutting edge (36) in a distal end (40) of the body, the body having at least one helical flute (16,18) formed therein at an angle relative to an axis of rotation that is greater than that of the at least one first flute (col. 2, lines 51-54 an col. 3, lines 10-13) and being formed in a second hand rotational direction opposite to the first hand directional rotation. Yeo '316 shows the at least one helical flute having at least one helical flute cutting edge (24,26) spaced radially apart from the at least one first flute cutting edge so that a leading portion of the cutting edges generally lie in a common radial plane. Yeo '316 shows the at least one first flute and first flute cutting edge being straight relative to the axis of rotation when the helix angle is approximately a 1 degree helix (col. 3, lines 10-13) and therefore equivalent to that defined by the Applicant in the specification (page 8, lines 15-24).

Regarding claim 4, Yeo '316 shows a longitudinal direction between the at least first flute cutting edge and the at least one helical flute cutting edge being less than 10 percent. Again based upon the relationship chosen between the helix angles of the first flute and helical cutting edges, a 10 percent or less relationship can be achieved (col. 3, lines 10-13).

Regarding claims 6,9 and 10, Yeo '316 shows a cylindrical margin (20,22,42), a longitudinal margin (42) generally aligned with the at least first flute, and a helical margin (20,22) generally aligned with the at least one helical flute for providing bearing support to the tool within the hole.

Regarding claims 13,17 and 18, Yeo '316 shows at least one primary relief surface (46) and at least one secondary relief surface (48) extending therefrom and formed along the at least one first flute cutting edge, and at least one relief surface (32,34) formed along the at least one helical flute cutting edge.

Regarding claims 14 and 16, Yeo '316 shows the at least one first flute cutting edge comprising a leading edge (50) inclined in relation to a radial plane and an end cutting edge (52)

Application/Control Number: 10/770,888

Art Unit: 3722

formed at an intersection of the first flute cutting edge and the distal end of the body (col. 3, lines 3-8).

Regarding claims 19-24, Yeo '316 shows the at least one first flute comprising an array of first flutes (28, only 1 of 2 shown) and the at least one helical flute comprising an array of helical flutes (16,18) wherein the respective array has an angular spacing tolerance (as defined by the Applicant on page 9, lines 2-8) between sequential flutes that is equal to or less than four radial quadrants divided by twice the number of respective flutes in the array in order to vary the loads imparted on the workpiece and tool. The number for both the first flutes and helical flutes is 2, therefore the angular spacing tolerance for each is equal to (360 / (2*2)) = 360 / 4 = 90 degrees which should be equal to or less than half the angular distance between respective flutes (180 degrees), which results in (1/2) * 180 degrees = 90 degrees.

Claims 1-10,13 and 18-29 are rejected under 35 U.S.C. 102(b) as being anticipated by Serwa 2002/0090273. Serwa 2002/0090273 shows in Figures 1-3 a rotary cutting tool (10) having a shank (18) for rotation in a first hand direction (A), a cylindrical body extending axially from shank having at least one first flute (24) with at least one first flute cutting edge (20) in a distal end (16) of the body, the body having at least one helical flute (26) formed therein at an angle relative to an axis of rotation that is greater than that of the at least one first flute (page 3, paragraph [0025]) and being formed in a second hand rotational direction opposite to the first hand directional rotation. Serwa 2002/0090273 shows the at least one helical flute having at least one helical flute cutting edge (22) spaced radially apart from the at least one first flute cutting edge so that a leading portion of the cutting edges generally lie in a common radial plane. Serwa 2002/0090273 shows the at least one first flute and first flute cutting edge being parallel or substantially parallel to the axis of rotation (page 3, paragraph [0025]) and therefore equivalent to that defined by the Applicant in the specification (page 8, lines 15-24).

Regarding claim 4, Serwa 2002/0090273 shows a longitudinal direction between the at least first flute cutting edge and the at least one helical flute cutting edge being less than 10 percent. Again based upon the relationship chosen between the helix angles of the first flute and helical cutting edges, a 10 percent or less relationship can be achieved (page 3, paragraph [0025]).

Regarding claims 6,9 and 10, Serwa 2002/0090273 shows in Figures 2 and 3 a cylindrical margin (not indexed), a longitudinal margin (not indexed) generally aligned with the at least first flute, and a helical margin (not indexed) generally aligned with the at least one helical flute for providing bearing support to the tool within the hole.

Regarding claims 7 and 8, Serwa 2002/0090273 shows in Figure 3 a negative rank angle for the first flute cutting edge (not indexed) and the helical flute cutting edge (not indexed).

Regarding claims 13 and 17, Serwa 2002/0090273 shows at least one primary relief surface (36) formed along the at least one first flute cutting edge, and at least one relief surface (34) formed along the at least one helical flute cutting edge.

Regarding claims 19-24, Serwa 2002/0090273 shows the at least one first flute comprising an array of first flutes (24,24) and the at least one helical flute comprising an array of helical flutes (26,26) wherein the respective array has an angular spacing tolerance (as defined by the Applicant on page 9, lines 2-8) between sequential flutes that is equal to or less than four radial quadrants divided by twice the number of respective flutes in the array in order to vary the loads imparted on the workpiece and tool. The number for both the first flutes and helical flutes is 2, therefore the angular spacing tolerance for each is equal to (360 / (2*2)) = 360 / 4 = 90 degrees which should be equal to or less than half the angular distance between respective flutes (180 degrees), which results in (1/2) * 180 degrees = 90 degrees.

Regarding claims 25 and 26, Serwa 2002/0090273 shows the number of first flutes can be any number desired, such as 3 or 5 flutes (page 4, paragraph [0033]).

Claim Rejections - 35 USC § 103

- 4. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
 - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.

Claim 11 is rejected under 35 U.S.C. 103(a) as being unpatentable over Yeo '316 in view of Reynolds et al. '458. Yeo '316 lacks the presence of at least one gash to assist in the removal of debris from the at least one helical flute cutting edge. Reynolds et al. '458 shows in Figures 1 and 2 a primary gash face (8) and a secondary gash face (10) serving the purpose of debris removal (col. 2, lines 32-44) from the helical flutes (5) at the body distal end (9). In view of this teaching of Reynolds et al. '458, it would have been obvious to include one or more gash faces shown by Reynolds et al. '458 to the rotary tool of Yeo '316 to facilitate debris removal so the tool could be operated at higher speeds with reduced wear, resulting in extended tool life.

Claim 12 is rejected under 35 U.S.C. 103(a) as being unpatentable over Yeo '316 in view of Magill et al. '712. Yeo '316 lacks the presence of a coolant channel for conveying coolant fluid to the cutting edges. Magill et al. '712 shows in Figure 5 a coolant passage (44) for conducting coolant to the cutting edges and the associated surface of the workpiece. In view of this teaching of Magill et al. '712, it would have been obvious to include a coolant passage shown by Magill et al. '712 to the rotary tool of Yeo '316 to provide cooling of the blades resulting in extended tool life.

Claim 15 is rejected under 35 U.S.C. 103(a) as being unpatentable over Yeo '316 in view of Miller '487. Yeo '316 lacks the presence of a pilot tip extending from the distal end.

Application/Control Number: 10/770,888

Art Unit: 3722

Miller '487 shows in Figure 1 a pilot tip (21) extending from the body distal end (18). In view of

this teaching of Miller '487, it would have been obvious to include a pilot tip shown by Miller '487

to provide bearing support to the rotary tool within the hole being formed.

Any inquiry concerning the content of this communication from the examiner should be 5.

directed to Michael W. Talbot, whose telephone number is 571-272-4481. The examiner's

office hours are typically 8:30am until 5:00pm, Monday through Friday. The examiner's

supervisor, Mr. Boyer D. Ashley, may be reached at 571-272-4502.

In order to reduce pendency and avoid potential delays, group 3720 is encouraging

FAXing of responses to Office Actions directly into the Group at FAX number 703-872-9306.

This practice may be used for filling papers not requiring a fee. It may also be used for filling

papers, which require a fee, by applicants who authorize charges to a USPTO deposit account.

Please identify Examiner Michael W. Talbot of Art Unit 3722 at the top of your cover sheet.

Michael W. Talbot

Examiner

Art Unit 3722

Page 7